


Spare parts for the rotary drum thickener

Siljan RotoMaster

The first Siljan RotoMaster drum thickener was taken into service in 1988; Experience shows that the service life of this machine as well as of components used is very long, more than 20 years. The major reason for that is its robust construction, in combination with the low rotation speed of the drum, only about 10 revolutions per minute.

Certain components may, however, need replacement within a 5-10 years period.



Components which may need replacement are:

- Spray nozzles for cleaning of the filter cloth; the spray nozzles can easily be cleaned if clogged; For a 5 year's service time, a full set of replacement nozzles can be supplied at delivery of a new machine.
- Shaft bearings; is self lubricating and has a service life of more than five years. An extra set of shaft bearings can be delivered with new machines.
- Filter cloth; has a service life of more than 10 years, if not mechanically damaged.

If, by any chance, failure of any other component does occur, Siljan Allards can, within short notice, deliver spare parts to such components as well as those mentioned above.

Please contact us for further information: